

# ANTENNA SPARK



cod. ACG5452 Mod.433  
cod. ACG5454 Mod.91



Fig. 1



Fig. 2



Fig. 3



Fig. 4



Fig. 5




Fig. 6



Fig. 7




Fig. 8

Cod. CM1526-28092002-Rev. 00

# ANTENNA SPARK



cod. ACG5452 Mod.433  
cod. ACG5454 Mod.91



Fig. 1



Fig. 2



Fig. 3



Fig. 4



Fig. 5



Fig. 6




Fig. 7




Fig. 8

Cod. CM1526-28092002-Rev. 00



Fig. 9



Fig. 10



Fig. 11



Fig. 12

**COMPANY  
WITH QUALITY SYSTEM  
CERTIFIED BY DNV  
=ISO 9001/2000=**



*automatismi per cancelli  
automatic entry systems*

® 25014 CASTENEDOLO (BS)-ITALY

Via Matteotti, 162

Telefono ++39.030.2135811

Telefax ++39.030.21358279-21358278

<http://www.ribind.it> - email: [ribind@ribind.it](mailto:ribind@ribind.it)



Fig. 9



Fig. 10



Fig. 11



Fig. 12

**COMPANY  
WITH QUALITY SYSTEM  
CERTIFIED BY DNV  
=ISO 9001/2000=**



*automatismi per cancelli  
automatic entry systems*

® 25014 CASTENEDOLO (BS)-ITALY

Via Matteotti, 162

Telefono ++39.030.2135811

Telefax ++39.030.21358279-21358278

<http://www.ribind.it> - email: [ribind@ribind.it](mailto:ribind@ribind.it)